



From the desk of the AYC Harbor Commander  
Joe Roddy  
(harbor\_commander@austinyachtclub.net)

October 2017

At this writing, we are in the process of pouring concrete ramp extensions to add length to the steps.

This will allow the dock ramps to continue to allow better access as the water levels drops. There will not be handrails in the early stage of this addition so please go slow and careful when using ramps.

There are still some issues with falling water levels in the south cove which has created some close quarters with the junior docks. We are working on this and have installed new anchors which should allow the docks to be placed further apart in the near term.

We still have some dry storage spots available but the Wet Slip storage is on a wait list for deeper draft and larger boats.

We would encourage Wet slip holders to please continue to monitor your dock lines for chafe and replacement if necessary. As you know, with fall comes more frequent winds from the North. These fronts tend to have strong winds and can do some damage if your boat has weakened dock lines.

Joe Roddy  
Harbor Commander

*This is an activity report of an individual board member and does not represent the official position of the Austin Yacht Club or its Board of Directors.*